

Category: Chemical Resistance

Customer: Shepherd Chemical

Product: Rhino Pipeliner 5000



INDUSTRIAL COATINGS

PROBLEM: Shepherd Chemical's filter press was damaged from corrosion due to hydrochloric acid exposure.

SOLUTION: TRIVACO applied Rhino Pipeliner 5000 @ 100 mil. The dense chemical structure of the coating gives it high impermeability and excellent corrosion and chemical resistance.



BEFORE



AFTER



TRIVACO | 2615 Arbor Tech Drive | Hebron, KY 41048 | 859 525 9890 | www.trivaco.com

TRIVACO – TSV Division
6833 Industry Drive
Indianapolis, IN 46219
T 317 356 2000

TRIVACO – TSE Division
146 Bluffs Court
Canton, GA 30114
T 770 479 4700

**TRIVACO – Oil & Gas
Service Division**
126 McColloch Street
Wheeling, WV 26003
T 888 463 7897